Maryland Historical Trust

Maryland Inventory of Historic Property Name: The bridge referenced herein was of the Historic Bridge Inventory, a February 2001. The Trust accepter received the following determinations.	nventoried by the M nd SHA provided the d the Historic Bridge	arylar	nd State st with e	High	way . lity d	Admi eterm	nistra inatio	ns in	
M Eligibility RecommendedX	ARYLAND HISTOI			ST lity No	ot Rec	comm	ended		
Criteria:ABC	_D Considerations: _	A .	B	-					
Comments:									
Reviewer, OPS:Anne E. Bruder					-		2001_		
Reviewer NR Program Peter E. Ki	ırtze			Date	:3	April	1 2001		_

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

SHA Bridge No. H-53	Bridge name Lake Fanny Road over Winters Run
LOCATION: Street/Road name and no	umber <u>Lake Fanny Road</u>
City/town Bel Air	VicinityX_
County Harford	
This bridge projects over	: Road Railway Water X
Ownership: State	X County Municipal Other
National Registe	designated historic district? Yes No _X er-listed district National Register-determined-eligible district ted district Other
BRIDGE TYPE: Timber Bridge Beam Bridge	: Truss -Covered Trestle Timber-And-Concrete
Stone Arch Bridge	
Metal Truss Bridge	
Movable Bridge Swing Vertical Lift	Bascule Single Leaf Bascule Multiple Leaf Retractile Pontoon
Metal Girder Rolled Girder Plate Girder	
Metal Suspension	
Metal Arch	
Metal Cantilever	
Concrete X : Concrete Arch_	X Concrete Slab Concrete Beam Rigid Frame
Other Type Name	

DESCRIPTION:

Describe Setting

Bridge H-53 carries Lake Fanny Road over Winters Run in Harford County. Lake Fanny Road runs north-south over the eastern flowing Winters Run. At this site there is limited commercial and residential development.

Describe Superstructure and Substructure:

Bridge H-53 is a single span filled concrete arch. The length of the bridge is approximately 53 feet with a clear span of 48 feet. The rise is approximately 12 feet 6 inches. The abutments are concrete and are approximately 24 feet wide and 13 feet high. The overall width of the bridge is 23 feet 6 inches.

According to a 1995 inspection report, the arch has medium to small size spalls along the barrel and spandrel wall joint. In addition, there is efflorescence along the spandrel walls, which also show signs of medium vertical and irregular cracks with small and medium areas of delamination. The bridge is considered to be in satisfactory condition with a sufficiency rating of 93.0.

This bridge has a closed panel type parapet. This type of reinforced concrete parapet consists of vertical posts securely fastened by dowels to the structure, horizontal balustrades, and solid panels that fill the space between the posts and the railings. Bridge H-53 has 8 paneled sections. Each section is approximately 4 feet long and 1 foot high, and is incised approximately 1 inch. The parapet is 2 feet 11 inches tall with a cap that is 1 foot by 4 feet 3 inches.

Discuss major Alterations:

There have been no major alterations to this structure except patching and mortar repair.

HISTORY:

This date is: Actual X	ctual date or date range) <u>1913</u> Estimated					
Source of date: Plaque _X	Design plans County bridge files/inspection form					
Other (specify)						
WHY was bridge built? Rep	placement of existing structure.					
WHO was the designer? Lut	iten Bridge Company					
WHO was the builder? Lute	ten Bridge Company					
	NT/A					
WHY was bridge altered? N	V/A					
J	NA an organized bridge-building campaign?					

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have National Register significance for its association with:

A - Events __X B- Person ___

C- Engineering/architectural character _X_

This bridge was determined eligible by the Interagency Review Committee in June 1996.

Was bridge constructed in response to significant events in Maryland or local history?

Yes, as Harford County and Bel Air expanded, the infrastructure needed to be improved. As the county expanded in population and the county needed to get its agricultural products to Baltimore City, better roads were needed. The Commissioners contracted the job of building a bridge over Winters Run to the Luten Bridge Company of York, Pennsylvania. The company was incorporated in 1909 as a contracting concern specializing in the designs of Daniel Luten. It grew to be the largest of Luten's loosely affiliated corporations and operated offices in Clarksburg, WV;

Concord, NH; Columbus, OH; Chatsworth, GA; and Syracuse, NY. Daniel Luten specialized in reinforced concrete bridges. His designs dominated the industry and were copied (under patent protection) and used throughout the eastern United States.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth & development of the area?

No, the bridge replaced an older structure, and did not have a significant impact on the growth and development of the area.

Is the bridge located in an area that may be eligible for historic designation?

No, the bridge is not located in an area that is eligible for historic designation.

Is the bridge a significant example of its type?

Yes, this bridge is a good example of the early concrete arch bridges designed by the Luten Bridge Company.

Does bridge retain integrity of important elements described in Context Addendum?

Although there is some minor shifting and deterioration in the arch, the bridge retains the character defining elements of its type, including parapets, arch ring, and spandrel walls.

Is bridge a significant example of work of manufacturer, designer and/or engineer?

Yes, this bridge has a marble plaque that dates the bridge to 1913. The plaque also lists the builder as the Luten Bridge Company of York, Pennsylvania. This was the parent company of Daniel Luten, one of the nation's pioneers in concrete bridge building.

Should bridge be given further study before significance analysis is made?

Yes, it is important to know how many of Luten's earliest structures are remaining throughout the region. There are very few that can be documented with a construction marker.

BIBLIOGRAPHY: County inspection/bridge files _____ SHA inspection/bridge files ____ X ____ Other (list):


SURVEYOR/SURVEY INFORMATION:

Date bridge recorded May 1996
Name of surveyor Stacie Webb

Organization/Address State Highway Administration, 707 North Calvert Street, Baltimore MD

Phone number 410-545-8559

Edited by P.A.C. Spero & Company, December 1997





+1,-1983 HARFORD COUNTY MD JOHN TARQUINIO 3/12/15 HALLEND SHED SHA -BRIDGE H53 OVER WINTERS RUN - VIEW LOOKING SOUTH ON LAKE FANNY RD



117-1963 HARFORD COUNTY, MD. JOHN TARQUINUD 3/12/95 HARRED SHPO-SHA - BROGE HES OVER WINTER'S RUN - YIEW LOOKING SOUTH ON LAKE FANINY ROAU

2/5



HARFORD COUNTY 140

JOHN TAROUNIC

3/12/95

HARFIERD SHA

- BRIDGE H53 OVER WINTER'S RUN

- VIEW LOOKING WEST

3/5



HA-1983
HARFORD COUNTY, HD

JOHNS TARQUINIO

3/12/95
HARYLAND SHIE SMA

- BRIDGE HS3 OVER WINTER'S ROID

- VIEW LOOKING E-157

4 5



HARFORD COUNTY, MO

JOHN TARQUINIO

3/12/95

HARMOND SHPO SHA

- BRIDGE H53 OVER WINTER'S RUN

- PLAQUE ON ELST PARAPET